

# Woodridge Village Development

## Completed Corrective Actions



Entrance/Exit at Webb Street; needs to be stabilized with rock



Entrance/Exit has been stabilized with rock; corrective actions completed





Drainage channel on west side of the northern cleared area near Webb Street; needs perimeter controls installed



Silt fence installed; corrective actions completed