

Maria Acevedo Maria Acevedo 7777 Plum Grove Rd Cleveland, TX 77327

P.O. Box 1089 Coldspring Tx 77331 Website: eastexlabs.com Email: eastexlab@eastex.net Tel: 936 653 3249



LABORATORY ANALYTICAL REPORT

Project: Maria Acevedo Ditch Monitoring

Sample Site:

Frances Ditch

Sample Number:

Collector:

DCH

Sample Type:

Grab

C0F4586-01

Sampled:

06/19/2020 • 11:10

Sample Matrix:

Water

Received:

06/19/2020 12:35

Client Matrix:

Water

Analyte

Reporting Limit

Nelac Units Status

Batch

Analyzed Analyst

Method

Notes

Result Fecal Coliform IDEXX 5120 100 mpn/100ml B0F2880 06/19/2020 14:30 ACW Colilert 18

Colilert 18 - Quality Control

Eastex Environmental Laboratory - Coldspring

Fecal Coliform IDEXX	4870	100 mpn/1	00ml	5120			5.01	200	
Duplicate (B0F2880-DUP1)	Sour	ce: C0F4586-01	Prepared a	& Analyzed:	06/19/20				
Fecal Coliform IDEXX	ND	I mpn/I	00ml						
Blank (B0F2880-BLK1)			Prepared a	& Analyzed	06/19/20				
Batch B0F2880 - No Prep Micro									
Analyte	Result	Limit Un	its Level	Result	%REC	Limits	RPD	Limit	Notes
		Reporting	Spike	Source		%REC		RPD	

Mar Burgêois

Mark Bourgeois, Special Projects Manager

Qualifiers



REPORT TO:

P.O. Box 1089 * Coldspring, TX 77331 (936) 653-3249 * (800) 525-0508

INVOICE TO:

EASTEX ENVIRONMENTAL LABORATORY, INC.

30x 1089 * Coldspring, TX 77331 P.O. Box 631375 * Nacogdoches, TX 75963-1375 (936) 653-3249 * (800) 525-0508 (936) 569-8879 * FAX (936) 569-8951 www.eastexlabs.com

White Copy-Follows Samples Yellow Copy-Laboratory Pink Copy-Client Copy

Remarks: C= Composite G= Grab DW=Drinking Water WW=Wastewater SO=Soil/Sludge OT=Other 1=Gallon 2=1/2 Gallon 3=QuarVLiter 4=500mL 5=250mL 6=125mL (4oz) 7=60mL (2 oz) 8= 40mL Vial 9=Other P= Plastic G= Glass T= Teflon S= Sterile C=Chilled S=Sulfuric Acid N=Nitric Acid B=Base/Caustic Z= Zn Acetate ST=Sodium Thiosulfate H=HCL O= Other
CC Cother Z= Zn Acetate
ANALYSIS REQUESTED

Date

Time

*Thermometer has 0.0 factor and recorded temperature is actual temperature